

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,858,927 B2
DATED : February 22, 2005
INVENTOR(S) : Prindiville et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page,

Item [57], **ABSTRACT**,

Line 8, "pressure sensitive" should be -- pressure-sensitive --.

Column 3,

Line 29, "(FIG. 2a and 2B)" should be -- (FIGS. 2A and 2B) --.

Column 5,

Line 35, "opening (see" should be -- opening, see --.

Column 6,

Lines 4 and 10-11, "defect substrates" should be -- defective substrates --.

Line 5, "sites are" should be -- sites) are --.

Column 8,


Line 12, "includes" should be -- include --.

Column 9,

Lines 3-4, "one individual defective substrate, wherein the defective pattern of conductors" should be -- one individual defective substrate, wherein the defective substrate has a defective pattern of conductors --.

Signed and Sealed this

Twenty-first Day of March, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office